Date		POKAI BAY	Survey Dates										
first used		OPOK 1-1	8/15/94	1/27/95	9/15/95	3/30/96	8/20/96	2/9/97	8/5/97	12/30/97	7/28/98	1/30/99	7/14/99
8/15/94	RP#1	Cement wall by road (old line)	RP1	RP1	-	-	-	-	-	-	-	-	-
8/15/94	RP#2	Mauka palm (old line)	RP2	RP2	-	-	-	-	-	-	-	-	-
8/15/94	RP#3	Makai palm (old line)	RP3	RP3	RP5	-	-	-	-	-	-	-	-
8/15/94	RP#4	Nail in cement wall by gate	RP4	-	RP3	-	-	-	-	-	-	-	-
8/15/94	RP#5	Rock wall by jetty - "T" in Patrick	RP5	RP5	-	-	-	-	-	-	-	-	-
1/27/95	RP#5A	8" landward of RP2	-	RP5a	-	-	-	-	-	-	-	-	-
8/15/94	RP#6	Cement base of fishing sign	RP6	-	RP3	-	-	-	-	-	-	-	-
1/27/95	RP#7	Sidewalk (online)	-	-	RP1	BRP	BRP	BRP	BRP	BRP	BRP	BRP	BRP
1/27/95	RP#8	Fence post top(ONLINE)	-	-	RP2	-	-	-	-	-	-	-	-
1/27/95	RP#9 **	nail in seaward Palm tree, online	-	-	FRP	FRP	FRP	FRP	*FRP	FRP	FRP	FRP	FRP
2/26/96	RP#10	Divot on sidewalk by 4th post	-	-	-	SRP	SRP	-	GPS1	GPS1	GPS1	SRP	GPS
2/26/96	RP#11	PK nail, Indwd side rod	-	-	-	GP2		GPS	GPS2	GPS2	-	-	-
	line number Start of Line		Α	Α	В	В	В	В	В	В	В		
			base.RP2	base.RP1	Indwd.rd	Indwd.rd	Indwd.rd	RP7	Indwd.rd	RP7	RP7	AT.BRP	-
	Bearing		234°	-	245°	260°	-	259°	273°	273°	275°		

= new PK or other marks

Line-up

Beach immediately N of Kaneilio Pt. in Pokai Bay. Access from Lualualei Homestead Rd, or at st. by NAPA Auto Parts. off Farrington Hwy

Line set 9/95 lines up with white tower on water tank on ridge in the background behind town and the 7th palm on the beach SE from aptments in a group of 3.

RP#1 Divot 1.75m from N end of low cement wall fronting SWD side of aptments. Divot is also 30cm N of wood fence. (old line)

RP#2 Seaward facing nail 1m up landward palm 1m seaward of cement wall and RP#1 in northmost group of palms. (old line)

RP#3 Seaward facing nail 1.5m up seawardmost palm in a line of 3 in northmost group of palms. (old line)

RP#4 Nail in crack at south end of low cement wall fronting seaward side of apartments between south corner of wall and south gate post.

RP#5 Divot in middle of "T" in "PATRICK" on top of 1.5m tall rock wall b/w N jetty & apartments, 45cm from corner fencepost & 20cm from swd edge.

RP#5a unknown marker 8 inches landward of RP2

RP#6 Bent nail in seaward side of cement base of fishing sign on north jetty.

RP#7 Center of 5 divots in sidewalk on line behind 2nd fence post north of gate (2 m N of edge of fence).

RP#8 Etched "X" on top of 2nd cyclone fence post north of gate accessing beach from street running N - S between apartments and beach park parking.

RP#9 SWS-facing nail (not screw) 1m up 7th palm SE of apartments. Palm is most north in group of three palms, 30' N of swing.

RP#10 Divot in center of "Y" mark in middle of sidewalk in line with 4th metal post N of beach access blocked by curb. Divot is ~5" N of sidewalk crack near grass.

RP#11 PK nail on landward side of road 1' from edge of road on not-recently-paved shoulder. Nail is in line with 4th fencepost N of beach access

GPS1 POK1 (aka PK1A) = RP10; New RP on sidewal landward of 4th fence post; divot in ceter of Y

GPS2 POK2 (aka PK2A) = RP11; PK on landward side of road, 1' from edge, 10' from brick fence base.

## NOTES:

2/26/96 GPS Survey. POK1, POK2

9/15/95 Established new line south of old line

\* This site has not been corrected to the local tidal datum

Preliminary GPS positions (not adjusted)

Longitude Latitude Elevation (relative to ellipsoid?)

POK1 -158.187363 21.443336 -13.491 POK2 -158.187286 21.443323 -13.665

<sup>\*\*</sup>Primary reference point; RP9/FRP = 0