Date		Kaiwaloa	Survey Dates											
first used		OKWO 1-1	8/10/94	1/17/95	9/14/95	3/10/96	8/22/96	3/2/97	8/6/97	12/29/97	7/21/98	1/28/99	7/9/99	
8/11/94	RP#1	Palm on edge of beach	RP#1	RP4	RP1	RP1	-	BSRP	BSRP	SRP	SRP	SRP	SRP	
8/11/94	RP#2	8th step from top (W/SWD corner)	RP#2	-	RP2	RP2	-	-	-	-	-	-	-	
8/11/94	RP#3 **	Palm in yard (61-669 Kam Hwy)	RP#3	RP3	BRP	BRP	BRP	BRP	RP3	-	BSRP	-	-	
8/11/94	RP#4	Concrete slab surrounding house	RP#4	-	RP4	-	-	-	-	-	-	-	-	
8/11/94	RP#5	Top Step of 61-661 Kam Hwy	RP#5	RP5	-	-	-	-	-	-	LOST	-	-	
1/17/95	RP#6 *	PK in concrete slab	-	GPS1	-	-	-	-	-	-	-	-	-	
3/10/96	RP#7 ***	Top Step of 61-669 Kam Hwy	-	-	-	NEW.SRP	BSRP	-	-	BRP	BRP	BRP	BRP?	
8/22/96	RP#8	W-SWD corner of bottom step (#9)	-	-	-	-	FSRP	FRP	FSRP	FRP	FRP	FRP	FRP?	
3/2/97	RP#9	E-SWD corner of bottom step (#9)	-	-	-	-	-	FSRP	-	-		-	-	
	Line Number Start of Line		Α	Α	Α	A	Α	В	A	С	С	C?	C?	
			base.RP3	base.RP3	near.RP3	base.steps	near.RP3	near.RP4	base.RP3	ON.RP8	ON.RP7	at.BRP	i T	
	bearing		328°	-	-	328°	-	328°	328°	320°	318°		1	
			* = new PK nail	or other marker										
Location:	Profile line	is stairs leading to beach at 61-669 K	am. Hwy. Access	beach from 61-	667B Kam Hwy	., across st. from	Meadow Gold							
LINE A:	Runs from I	Runs from RP3 tree offshore, lined up with MS												
LINE B:	Runs from I	RP3 to RP8not shore-normal												
LINE C:	Runs along	Runs along west side of stairs												
		lail 1m up on NNE side of palm located 4m mN of stairs near yeq. line												

RP#2 Chip on west seaward corner of 2nd step from bottom (8th from top). 2" in diagonally.

RP#3 Nail at 1.5m on seaward side of palm in N side of backyard of 61-669 Kam Hwy.

RP#4 Landward corner of westernmost edge of concrete slab surrounding #61-667B house. 2m landward of cassarina.

RP#5 West landward corner of top concrete step of beach stairs at 61-661 home.

RP#6 PK in concrete slab surrounding #61-667B house west of beach stairs/GPS1

RP#7 West seaward corner of top step of beach stairs at 61-669 Kam Hwy

RP#8 West-seaward corner of bottom step of beach stairs (#9) at 61-660 Kam Hwy.

RP#9 East-seaward corner of bottom step of beach stairs (#9) at 61-660 Kam Hwy.

GPS1 OKWL (aka KWL1): RP6, PK nail in crack in sidewalk, 2m west, 0.5m south of grass

GPS2 KWL2: In sand online

NOTES:

1/17/95 GPS survey. Some uncertainty in locations.

1/28/99 No survey line identified

7/9/99 No survey line identified.

No RPs identified.

GPS Positions Longitude Latitude Elevation (meters above local tidal datum)

OKWL -158.088745 21.616051 5.266

KWL2 no position calculated

* Primary GPS for elevation control; RP6/GPS1 = 5.266

** LINES A and C: Primary reference point; RP3/BRP = 6.767

***LINE B: Primary refernce point RP7/BRP = 5.241 (March96)