5/18/00 BRP - - - -													
-													
-													
_													
-													
-													
FRP													
at FRP													
-													
Kaanapali Beach Hotel roof, at joint of peak													
PK nail on orange flag in intersection of 15th crack SWD from SWD end of straight path and center crack in middle of path.													
unmarked point on path													
K nail on orange flag at S end of thick crack (3rd on straight path) where straight path to road meets curved path along beach enter of pipe hole along shore-perpendicular crack; brush off sand, 1 ft LNDWD of 3rd crack along straight path to road													
marked point on sand													
PK nail on top/center of round support to brown wooden sign to N of path; GONE PK nail at SWD end of 25th crack to S along concrete walkway paralleling beach, near palm tree and just S of Kaanapali Beach Hotel													
RP5, KNP1 (1/12/95) RP2, KNP2 (1/12/95)													
l													
1													